



VEHICLE APPRAISAL REPORT

VEHICLE DETAILS

Vin Number	XL RTEH4300G126374	Plate	B511BBS	Odometer	1218803
Make	Daf	Model	XF	Body Type/Doors	Utilitara de mare capacitate/2
Registration Date	09/11/2016	Interior Colour	Black	Exterior Colour	Black
Smog Certificate Date	18/07/2024	Maintenance Odometer	0	Maintenance Date	18/07/2024
Gears	0	Gear Type	Automată	Seats	2
Fuel Type	Diesel	Drive	Tracțiune spate	HP	510 / 375

INSPECTION DETAILS

Inspection Date	18/07/2024 11:23:48	Inspection Location	TRITON INTERNATIONAL CARGO SRL
-----------------	---------------------	---------------------	--------------------------------



DOCUMENT LIST

Audio Manual	✗	Delivery Condition Report	✗
Emmissions Cert	✗	Euro Sticker	✗
Insurance	✗	Original Key	✓
Owners Manual	✗	Registration Form	✗
Service Manual	✗	Spare Key	✗
Tax Sticker	✗	Transport Licence	✗

ACCESSORIES

ABS	✓	Air-Conditioning	✓
Audio AM/FM Stereo	✓	Automatic Transmission	✓
Central Locking	✓	Cruise Control	✓
Dashboard Computer	✓	Fog Lights	✓
Front Electric Window	✓	Key Remote Entry	✓
Leather Upholstery	✓	Multifunctional Steering Wheel	✓
Outside Mirror Heating	✓	Outside Mirror Power	✓
Power Steering	✓		

REMOVABLE ITEMS

TYRES

Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Front Left	9 mm	Michelin	22	385/65	Summer
Front Right	9 mm	Michelin	22	385/65	Summer
Inner Rear Left	9 mm	Goodyear	22	315/80	Winter
Inner Rear Right	9 mm	Goodyear	22	315/80	Winter
Rear Left	9 mm	Goodyear	22	315/80	Winter
Rear Right	9 mm	Goodyear	22	315/80	Winter

EXCEPTION / DAMAGE

1		Part	Door - Left Front	Type	Scratch	Severity	10 cm - 15 cm	Repair Mode	No Action	Cause	In Service
2		Part	Roof - Top	Type	Dent	Severity	10 cm - 15 cm	Repair Mode	No Action	Cause	In Service
3		Part	Bumper - Front	Type	Scratch	Severity	10 cm - 15 cm	Repair Mode	No Action	Cause	In Service
4		Part	Fog Lamp - Front	Type	Moulding/Emblem/Strip Damage	Severity	4 cm - 6 cm	Repair Mode	No Action	Cause	In Service
5		Part	Rocker Panel - Right Front	Type	Scratch	Severity	15 cm - 20 cm	Repair Mode	No Action	Cause	In Service
6		Part	Side View Mirror - Right Front	Type	Scratch	Severity	10 cm - 15 cm	Repair Mode	No Action	Cause	In Service
7		Part	Fender / Wing - Right Rear	Type	Broken	Severity	Over 30 cm	Repair Mode	No Action	Cause	In Service
8		Part	Fender / Wing - Right Rear	Type	Peeling Paint	Severity	Over 30 cm	Repair Mode	No Action	Cause	In Service

9		Part	Fender / Wing - Left Rear
		Type	Peeling Paint
		Severity	Over 30 cm
		Repair Mode	No Action
		Cause	In Service
10		Part	Fender / Wing - Left Rear
		Type	Broken
		Severity	Over 30 cm
		Repair Mode	No Action
		Cause	In Service
11		Part	Side Panel - Left Rear
		Type	Dented w/ Paint Dmg
		Severity	10 cm - 15 cm
		Repair Mode	No Action
		Cause	In Service

INTERIOR DAMAGES

INSPECTION CHECKLIST

Smoker : No
Vehicle Not Driveable : No

COMMENTS

Volan uzat,+2 Paturi,Auto a fost inspectat in locatia CAT autologistik,+Frigider,Baterie descarcata,Pornire motor – da ,Funct. lumini –da ,Funct. geamuri – da ,Funct. Oglinzi - da, Servo - da, Sist. audio – da ,Martori bord aprinsi -da,Zgomot anormal motor -da, Capac capsulare motor -,nu Element insonorizare capota –nu,Cutie de viteze-automata, Frane normal, Esapament - normal, Centuri de sig. -da.



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard




Standard




Standard



Standard



Standard



Standard



Standard



Standard



Ref 1 ;



Ref 1 ;



Ref 2 ;



Ref 2 ;



Ref 3 ;



Ref 3 ;



Ref 4 ;



Ref 4 ;



Ref 5 ;



Ref 5 ;



Ref 6 ;



Ref 6 ;



Ref 7 ;



Ref 7 ;



Ref 8 ;



Ref 8 ;



Ref 9 ;




Ref 9 ;



Ref 10 ;



Ref 10 ;



Ref 11 ;



Ref 11 ;