

VEHICLE APPRAISAL REPORT









VEHICLE DETAILS					
Vin Number	XLRTEH4300G105823	Plate	B112XNG	Odometer	919509
Make	DAF	Model	XF	Body Type/Doors	Utilitaria de mare capacitate/2
Registration Date	14/04/2016	Interior Colour	Black	Exterior Colour	White
Smog Certificate Date	05/08/2024	Maintenance Odometer	0	Maintenance Date	05/08/2024
Gears	0	Gear Type	Automată	Seats	2
Fuel Type	Diesel	Drive	Tracțiune spate	HP	463 / 340

INSPECTION DETAILS			
Inspection Date	05/08/2024 15:20:59	Inspection Location	TRITON INTERNATIONAL CARGO SRL



DOCUMENT LIST		ACCESSORIES		REMOVABLE ITEMS					
Audio Manual	✗	Delivery Condition Report	✗	ABS	✓	Air-Conditioning	✓		
Emmissions Cert	✗	Euro Sticker	✗	Audio AM/FM Stereo	✓	Automatic Transmission	✓		
Insurance	✗	Original Key	✓	Central Arm Rest	✓	Central Locking	✓		
Owners Manual	✗	Registration Form	✗	Cruise Control	✓	Front Electric Window	✓		
Service Manual	✗	Spare Key	✗	Key Remote Entry	✓	Multifunctional Steering Wheel	✓		
Tax Sticker	✗	Transport Licence	✗	Outside Mirror Power	✓	Power Steering	✓		
				Sun Roof	✓				

TYRES						
	Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
	Front Left	7 mm	Continental	22	385/55	Summer
	Front Right	7 mm	Semperit	22	385/55	Summer
	Inner Rear Left	7 mm	Marca nerecunoscuta	22	315/70	Summer
	Inner Rear Right	7 mm	Marca nerecunoscuta	22	315/70	Summer
	Rear Left	7 mm	Marca nerecunoscuta	22	315/70	Summer
	Rear Right	7 mm	Marca nerecunoscuta	22	315/70	Summer

EXCEPTION / DAMAGE			
1		Part Type Severity Repair Mode Cause	Pillar - Left Front Rust 4 cm - 6 cm No Action In Service
2		Part Type Severity Repair Mode Cause	Door - Left Front Scratch 10 cm - 15 cm No Action In Service
3		Part Type Severity Repair Mode Cause	Side View Mirror - Left Front Scratch Over 30 cm No Action In Service
4		Part Type Severity Repair Mode Cause	Bumper - Front Rust Over 30 cm No Action In Service
5		Part Type Severity Repair Mode Cause	Bumper - Front Moulding/Emblem/Strip Damage 4 cm - 6 cm No Action In Service
6		Part Type Severity Repair Mode Cause	Bumper - Front Dent 15 cm - 20 cm No Action In Service
7		Part Type Severity Repair Mode Cause	Bumper - Front Moulding/Emblem/Strip Damage 10 cm - 15 cm No Action In Service
8		Part Type Severity Repair Mode Cause	Pillar - Right Rear Moulding/Emblem/Strip Missing Missing No Action In Service

Part	Tyre - Right Rear
Type	Moulding/Emblem/Strip Damage
Severity	3 cm - 4 cm
Repair Mode	No Action
Cause	In Service

Part	Side Panel - Left Rear
Type	Scratch
Severity	Over 30 cm
Repair Mode	No Action
Cause	In Service

INTERIOR DAMAGES

INSPECTION CHECKLIST

Smoker : No

Vehicle Not Driveable : No

COMMENTS

Volan uzat,+2 Paturi,Auto a fost inspectat in locatia CAT autologistik,+Frigider,Baterie descarcata,Auto porneste greu,Pornire motor – da ,Funct. lumini –da ,Funct. geamuri – da ,Funct. Oglinzi - da, Servo - da, Sist. audio – da ,Martori bord aprinsi -da,Zgomot anormal motor -da, Capac capsulare motor -,nu Element insonorizare capota –nu,Cutie de viteze-automata, Frane normal, Esapament - normal, Centuri de sig. -da.

