

VEHICLE APPRAISAL REPORT

VIN	WDF44781513435474	Licence Plate	B250AKS	Fuel Type	Diesel
Make	MERCEDES-BENZ	Odometer	160346	Body Type	estate
Model	V-Klasse	Exterior Colour	Black	Interior Colour	Brown
Series	V 250 CDI 7G-TRONIC	ETG Code	10382983	Paint Category	
Year	2018	HP	190 / 140	Engine Displacement	2143
Doors	5	Seats	7	Drive	rear-wheel drive
Gears	7	Trans	Automată	Eng. Cyl	4
Cyl. Arrangement	Inline	Trim		Country of Registration	
Country of Manufacture					
Turbo / Supercharged:	Turbo	Technical Check Exp.	12/03/2024	Maintenance	0
Maintenance Date		Parking Bay.		Company Name	Raiffeisen Leasing
Inspection Loc.	TRITON INTERNATIONAL CARGO SRL	Arrival Date	12/03/2024 17:10:47	Address	Calea Floreasca 246D
		Address		Registration Date	31/07/2018
City	Bucuresti	City		Manufacture Date	31/07/2018
State / Province, Zip		State / Province, Zip		Inspector No - ID	4128 - 5005125
Phone #	021.365.32.87	Phone #		Assgn. Date	
CR Post Date		MVI	0	Insp. Date	12/03/2024 17:10:47
Print Date		Test Certificate No.		W-Number	
Place of Storage	TRITON INTERNATIONAL CARGO SRL				

ACCESSORIES

8 Airbag	ABS	Air Condition Automatic	Alloy wheels	Audio CD Player
Automatic Transmission	Central Arm Rest	Central Locking	Cruise Control	Dashboard Computer
Deck Lid Power	Front Electric Window	Heated Seats	Key Remote Entry	Leather Upholstery
Lights Xenon	Multifunctional Steering Wheel	Navigation System	Outside Mirror Heating	Outside Mirror Power
Parking Sensors	Power Steering	Steering Wheel Leather		

TYRES

Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Front Left	5 mm	Marca nerekunoscuta	17	245/45	Summer
Front Right	5 mm	Marca nerekunoscuta	17	245/45	Summer
Rear Left	5 mm	Marca nerekunoscuta	17	245/45	Summer
Rear Right	5 mm	Marca nerekunoscuta	17	245/45	Summer

EXCEPTION / DAMAGE

Ref	Part	Type	Severity	Comments
1	Door - Left Front	Scratch	8 cm - 10 cm	
2	Tyre - Left Front	Moulding/Emblem/Strip Damage	4 cm - 6 cm	
3	Bumper - Front(Right)	Scratch	Over 30 cm	
4	Windshield - Front	Broken	1 cm - 2 cm	
5	Door - Right Front	Dented, No Pnt Dmg	Over 30 cm	
6	Door - Right Rear(Right)	Dented, No Pnt Dmg	Over 30 cm	
7	Fender / Wing - Right Rear	Dented, No Pnt Dmg	Over 30 cm	
8	Bumper - Rear(Right)	Broken	15 cm - 20 cm	
9	Tailgate (Hatchback) - Rear	Scratch	10 cm - 15 cm	
10	Door Trim Panel - Left Front	Moulding/Emblem/Strip Damage	4 cm - 6 cm	
11	Seat - Right Front	Moulding/Emblem/Strip Damage	1 cm - 2 cm	

Comments

Auto murdar-posibil daune ascunse,Volan uzat,Pornire motor -da ,Funct. lumini -da ,Funct. geamuri - da ,Funct. Oglinzi - da, Servo - da, Sist. audio - da ,Martori bord aprinsi - da(carburant),Zgomot anormal motor -da, Capac capsulare motor - nu, Element insonorizare capota -da, Cutie de viteze-automata, Frane normal, Esapament - normal, Centuri de sig. -da.

Inspection Checklist

Smoker : No

Present ☒ Missing ☐

Anti-Theft Code	☐	Audio Manual	☐
Certificate of Conformity	☐	Delivery Condition Report	☐
Emmissions Cert	☐	Euro Sticker	☐
Insurance	☐	Original Key	☒
Owners Manual	☐	Radio Code	☐
Registration Form	☐	Service Manual	☐
Spare Key	☐	Tax Sticker	☐
Transport Licence	☐		

									
Standard		Standard		Standard		Standard		Standard	
									
Standard		Standard		Standard		Standard		Standard	
									
Standard		Standard		Standard		Standard		Standard	
									
Standard		Standard		Standard		Standard		Standard	
									
Standard		Standard		Ref 1 ;		Ref 1 ;		Ref 2 ;	
									
Ref 2 ;		Ref 3 ;		Ref 3 ;		Ref 4 ;		Ref 4 ;	
									
Ref 5 ;		Ref 5 ;		Ref 6 ;		Ref 6 ;		Ref 7 ;	
									
Ref 7 ;		Ref 8 ;		Ref 8 ;		Ref 9 ;		Ref 9 ;	
									
Ref 10 ;		Ref 10 ;		Ref 11 ;		Ref 11 ;			