



VEHICLE APPRAISAL REPORT

VEHICLE DETAILS					
Vin Number	XL RTEH4300G242376	Plate	B192GRC	Odometer	540670
Make	DAF	Model	XF	Body Type/Doors	Utilitara de mare capacitate/2
Registration Date	01/01/2018	Interior Colour	Black	Exterior Colour	White
Smog Certificate Date	08/05/2024	Maintenance Odometer	0	Maintenance Date	08/05/2024
Gears	0	Gear Type	Automată	Seats	2
Fuel Type	Diesel	Drive	Tracțiune spate	HP	483 / 355

INSPECTION DETAILS		
Inspection Date	08/05/2024 11:29:46	Inspection Location
		TRITON INTERNATIONAL CARGO SRL



DOCUMENT LIST				ACCESSORIES				REMOVABLE ITEMS			
Audio Manual	✗	Delivery Condition Report	✗	1 Airbag	✓	ABS	✓				
Emmissions Cert	✗	Euro Sticker	✗	Air-Conditioning	✓	Automatic Transmission	✓				
Insurance	✗	Original Key	✓	Central Arm Rest	✓	Central Locking	✓				
Owners Manual	✗	Registration Form	✗	Cruise Control	✓	Dashboard Computer	✓				
Service Manual	✗	Spare Key	✗	Front Electric Window	✓	Multifunctional Steering Wheel	✓				
Tax Sticker	✗	Transport Licence	✗	Outside Mirror Heating	✓	Outside Mirror Power	✓				
				Power Steering	✓	Sun Roof	✓				

TYRES					
Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Front Left	7 mm	Michelin	22	385/55	Summer
Front Right	7 mm	Michelin	22	385/55	Summer
Inner Rear Left	7 mm	Pirelli	22	315/70	Summer
Inner Rear Right	7 mm	Pirelli	22	315/70	Summer
Rear Left	7 mm	Pirelli	22	315/70	Summer
Rear Right	7 mm	Pirelli	22	315/70	Summer

EXCEPTION / DAMAGE					
1		Part	Door - Left Front	2	
		Type	Scratch		
		Severity	Over 30 cm		
		Repair Mode	No Action		
		Cause	In Service		
3		Part	Bumper - Front	4	
		Type	Scratch		
		Severity	Over 30 cm		
		Repair Mode	No Action		
		Cause	In Service		
5		Part	Rocker Panel - Right Front	6	
		Type	Scratch		
		Severity	Over 30 cm		
		Repair Mode	No Action		
		Cause	In Service		
7		Part	Side View Mirror - Right Front	8	
		Type	Broken		
		Severity	Over 30 cm		
		Repair Mode	No Action		
		Cause	In Service		

9		Part	Pillar - Right Front
		Type	Moulding/Emblem/Strip Missing
		Severity	Missing
		Repair Mode	No Action
		Cause	In Service
10		Part	Fender / Wing - Right Rear
		Type	Moulding/Emblem/Strip Missing
		Severity	Over 30 cm
		Repair Mode	No Action
		Cause	In Service
11		Part	Fender / Wing - Left Rear
		Type	Moulding/Emblem/Strip Missing
		Severity	Over 30 cm
		Repair Mode	No Action
		Cause	In Service
12		Part	Side Panel - Left Rear
		Type	Dent
		Severity	8 cm - 10 cm
		Repair Mode	No Action
		Cause	In Service

INTERIOR DAMAGES

13		Part	Dash Board - Foward
		Type	Moulding/Emblem/Strip Missing
		Severity	Missing
		Repair Mode	No Action
		Cause	In Service

INSPECTION CHECKLIST

Smoker : No
Vehicle Not Driveable : No

COMMENTS

Volan uzat,+2 Paturi,+Frigider,Baterie descarcata,Pornire motor – nu ,Funct. lumini –da ,Funct. geamuri – da ,Funct. Oglinzi - da, Servo - da, Sist. audio – da ,Martori bord aprinsi -da,Zgomot anormal motor -, Capac capsulare motor -,nu Element insonorizare capota –nu,Cutie de viteze-automata, Frane normal, Esapament - normal, Centuri de sig. -da.



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Ref 1 ;



Ref 1 ;



Ref 2 ;



Ref 2 ;




Ref 3 ;



Ref 3 ;



Ref 4 ;



Ref 4 ;



Ref 5 ;



Ref 5 ;



Ref 6 ;



Ref 6 ;



Ref 7 ;



Ref 7 ;



Ref 8 ;



Ref 8 ;



Ref 9 ;



Ref 9 ;



Ref 10 ;



Ref 10 ;



Ref 11 ;



Ref 11 ;




Ref 12 ;



Ref 12 ;



Ref 13 ;



Ref 13 ;