

VEHICLE APPRAISAL REPORT













VEHICLE DETAILS			
Vin Number	ZCFCL35A705493727	Plate	B150MED
Make	IVECO	Model	Daily
Registration Date	23/02/2023	Interior Colour	Black
Smog Certificate Date	07/02/2025	Maintenance Odometer 0	
Gears	6	Gear Type	Transmisie manuală
Fuel Type	Diesel	Drive	Tracțiune spate
Odometer	236005	Body Type/Doors	Platforma utilitara/2
		Exterior Colour	White
		Maintenance Date	07/02/2025
		Seats	3
		HP	136 / 100





INSPECTION DETAILS			
Inspection Date	07/02/2025 15:08:31	Inspection Location	TRITON INTERNATIONAL CARGO SRL



DOCUMENT LIST		ACCESSORIES		REMOVABLE ITEMS	
Audio Manual	✗	Delivery Condition Report	✗	1 Airbag	✓
Emmissions Cert	✗	Euro Sticker	✗	Air-Conditioning	✓
Insurance	✗	Original Key	✓	Central Locking	✓
Owners Manual	✓	Registration Form	✗	Front Electric Window	✓
Service Manual	✗	Spare Key	✗	Outside Mirror Power	✓
Tax Sticker	✗	Transport Licence	✗	ABS	✓
				Audio AM/FM Stereo	✓
				Dashboard Computer	✓
				Key Remote Entry	✓
				Power Steering	✓

TYRES					
Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Spare	8 mm	Marca nerecunoscuta	16	225/65	Summer
Front Left	6 mm	Laurent	16	225/65	Winter
Front Right	6 mm	Laurent	16	225/65	Winter
Rear Left	5 mm	Michelin	16	225/65	Winter
Rear Right	5 mm	Michelin	16	225/65	Winter

EXCEPTION / DAMAGE					
1		Part	Side View Mirror - Left Front	2	
		Type	Moulding/Emblem/Strip Damage		
		Severity	4 cm - 6 cm		
		Repair Mode	Remove & Replace		
		Cause	In Service		
3		Part	Wheel Cover - Right Front	4	
		Type	Missing		
		Severity	Missing		
		Repair Mode	Remove & Replace		
		Cause	In Service		
2		Part	Windshield - Front	5	
		Type	Chipped		
		Severity	1 cm - 2 cm		
		Repair Mode	Remove & Replace		
		Cause	In Service		
4		Part	Indicator Lamp - Left Rear	6	
		Type	Moulding/Emblem/Strip Missing		
		Severity	Missing		
		Repair Mode	Remove & Replace		
		Cause	In Service		
5		Part	Seat - Left Front	6	
		Type	Stained / Soiled		
		Severity	Over 30 cm		
		Repair Mode	Clean		
		Cause	In Service		
6		Part	Seat - Right Front	6	
		Type	Stained / Soiled		
		Severity	Over 30 cm		
		Repair Mode	Clean		
		Cause	In Service		

INTERIOR DAMAGES					
5		Part	Seat - Left Front	6	
		Type	Stained / Soiled		
		Severity	Over 30 cm		
		Repair Mode	Clean		
		Cause	In Service		
6		Part	Seat - Right Front	6	
		Type	Stained / Soiled		
		Severity	Over 30 cm		
		Repair Mode	Clean		
		Cause	In Service		

INSPECTION CHECKLIST	
Smoker : No	Vehicle Not Driveable : No

COMMENTS
Volan uzat,+1 Pat,Webasto,Auto a fost inspectat in service-ul CB AUTOCARE situat in Voluntari ,Pornire motor – da ,Funct. lumini –da ,Funct. geamuri – da ,Funct. Oglinzi - da, Servo - da, Sist. audio – da ,Martori bord aprinsi -da,Zgomot anormal motor -da, Capac capsulare motor -,nu Element insonorizare



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Ref 1 ;



Ref 1 ;



Ref 2 ;



Ref 2 ;



Ref 3 ;



Ref 3 ;



Ref 4 ;



Ref 4 ;




Ref 5 ;



Ref 5 ;



Ref 6 ;



Ref 6 ;