



## FIAT DUCATO

VIN	ZFA25000002U42865
Registration	B337MED
Mileage	277,539 km
First registration date	03/03/2022
Body colour	White

## INSPECTION DETAILS

Inspection date 20/05/2025 10:22:48

## VEHICLE INFO

Make	Fiat	Fuel type	Diesel
Model	Ducato	Mileage	277,539 km
VIN	ZFA25000002U42865	Number of seats	3
Registration	B337MED	Interior colour	Black
First registration date	03/03/2022	Body colour	White

## DOCUMENTS AND MAINTENANCE

Number of keys total	1	Registration certificate original	Yes	Type of Maintenance book	Digital maintenance
----------------------	---	-----------------------------------	-----	--------------------------	---------------------

## EQUIPMENT ACCORDING TO INSPECTOR

Abnormal engine noises	Yes	Head-up Display	No	Steering wheel multifunctional	Yes
Adaptive cruise control	Yes	Metalic paint	No	Type of climate control	Manual climate control
Airco functioning	No	Mirrors functioning	Yes	Type of headlighting	Headlighting Halogen
All seatbelts functional, damage free	All seatbelts OK	Number of charging cables (normal)	0	Type of Lining	Lining fabrics
Cruise Control	Yes	Number of charging cables (rapid charge)	0	Type of Tow bar	Tow bar fixed
First aid kit	No	Power steering functioning	Yes	Vehicle running	No
Functioning headlight L	Yes	Radio multimedia	Yes	Windows electric F	Yes
Functioning headlight R	Yes	Spare wheel	Yes	Windows electric functioning	Yes

# TIRES

Position	Tread	Manufacturer	Dimensions	Tire season	Type of rims	Runflat
Front Left	5.0 mm	Michelin	215/75 R 16 116 R	Winter	Steel	No
Front Right	5.0 mm	Michelin	215/75 R 16 116 R	Winter	Steel	No
Rear Left	5.0 mm	Michelin	215/75 R 16 116 R	Winter	Steel	No
Rear Right	5.0 mm	Michelin	215/75 R 16 116 R	Winter	Steel	No
Spare wheel	5.0 mm	Other	215/75 R 16 116 R	Summer	Steel	-

# EXTERIOR DAMAGES



## 4 | BUMPER F

Type	Scratch(es)
Repair mode	Replace




## 5 | GRILLE FRAME

Type	Scratch(es)
Repair mode	Replace



## 6 | HEADLIGHT L

Type	Scratch(es)
Repair mode	Acceptable



## 7 | WINDSCREEN

Type	Crack
Repair mode	Replace



## 8 | WING TRIM FL

Type	Stone chip(s)
Repair mode	Paint



## 9 | SIDE WALL RL

Type	Deformed / Strained
Repair mode	No repair



### 10 | BOOT DOOR PANEL RR

Type	Forced
Repair mode	No repair



### 12 | OUTSIDE REAR-VIEW MIRROR R, COMPLETE

Type	Crack
Repair mode	Replace



### 13 | WHEEL ARCH COVER RR

Type	Missing
Repair mode	Replace



### 14 | TOP

Type	Crack
Repair mode	No repair



### 15 | AERIAL


Type	Missing
Repair mode	Replace

## INTERIOR DAMAGES




### 1 | CD NAVIGATION

Type	Not original part
Repair mode	Replace



### 2 | STEERING WHEEL

Type	Broken
Repair mode	Replace



### 3 | SEAT COVER FL

Type	Worn
Repair mode	Acceptable



### 11 | BOOT COVER

Type	Tear
Repair mode	No repair

## COMMENTS

### **i** INSPECTOR COMMENTS

Auto prezinta zgârieturi și infundături superficiale, Martori bord aprinși-da(multiple erori).

# COMMERCIAL PHOTOS

