



DAF DAF.XF

XF EURO 6

VIN	XLRTEH4300G129025
Registration	B122RUT
Mileage	838,565 km
First registration date	27/10/2016
Body colour	Yellow

INSPECTION DETAILS

Inspection date	25/08/2025 14:03:27	Inspection location	Parc Benga (CAT)
-----------------	---------------------	---------------------	------------------

VEHICLE INFO

Make	DAF	Fuel type	Diesel
Model	DAF.XF	Mileage	838,565 km
Version	XF EURO 6	Number of seats	2
VIN	XLRTEH4300G129025	Interior colour	Black
Registration	B122RUT	Body colour	Yellow
First registration date	27/10/2016		

DOCUMENTS AND MAINTENANCE

Number of keys total	1	Type of Maintenance book	Maintenancebook missing
Registration certificate original	Yes	User's manual	No

EQUIPMENT ACCORDING TO INSPECTOR

Abnormal engine noises	Yes	Number of charging cables (rapid charge)	0
Adaptive cruise control	Yes	Power steering functioning	Yes
Airco functioning	No	Radio multimedia	Yes
All seatbelts functional, damage free	All seatbelts OK	Steering wheel multifunctional	Yes
Cruise Control	Yes	Type of climate control	Manual climate control

First aid kit	No
Functioning headlight L	Yes
Functioning headlight R	Yes
Head-up Display	No
Metalic paint	No
Mirrors functioning	Yes
Number of charging cables (normal)	0

Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of Tow bar	No Tow bar
Vehicle running	No
Windows electric F	Yes
Windows electric functioning	Yes


TIRES

Mounted Tires

Location	Position	Tread	Manufacturer	Dimensions	Tire season	Type of rims	Runflat
Front	Left	9.0 mm	Falken	385/55 R 22 160 K	Winter	Steel	No
Front	Right	8.0 mm	Falken	385/55 R 22 160 K	Winter	Steel	No
Rear	Left	8.0 mm	Other	295/60 R 22 160 K	Winter	Steel	No
Rear	Right	8.0 mm	Other	295/60 R 22 160 K	Winter	Steel	No

DAMAGES

Exterior damages



4 | Bumper moulding FL

Type

Scratch(es)

Repair mode

Acceptable



5 | Bumper moulding FR

Type

Scratch(es)

Repair mode

Acceptable




6 | Bumper FL

Type

Scratch(es)

Repair mode

Acceptable



7 | Windscreen

Type

Crack

Repair mode

No repair




8 | Door FL

Type

Scratch(es)

Repair mode

Acceptable



9 | Side wall RL

Type

Crack

Repair mode

Acceptable



10 | Wheel arch cover RL

Type

Crack

Repair mode

Acceptable



11 | Wheel arch cover RR

Type

Crack

Repair mode

Acceptable



12 | Right side

Type

Crack

Repair mode

Acceptable



13 | Side wall RR

Type

Crack

Repair mode

Acceptable

Interior damages



1 | Interior


Type

Missing

Repair mode

Acceptable

Comments: Dauna se referă la frigiderul de pe masina .



2 | Interior

Type

Missing

Repair mode

Acceptable

Comments: Dauna se referă la sirocoul .



3 | Interior

Type

Broken

Repair mode

No repair

COMMENTS

i Inspector comments

Auto pornește foarte greu posibile daune mecanice și tehnice rog verificare service autorizat, Lipsa multiple componente.

Commercial photos

