




VEHICLE APPRAISAL REPORT

VEHICLE DETAILS

Vin Number	WAUZZZF43LA071927	Plate	B912FST	Odometer	124998
Make	AUDI	Model	A 4	Body Type/Doors	estate/5
Registration Date	22/07/2020	Interior Colour	Black	Exterior Colour	Blue
Smog Certificate Date	12/06/2024	Maintenance Odometer	0	Maintenance Date	12/06/2024
Gears	1	Gear Type	Automată	Seats	5
Fuel Type	Diesel+Hibrid	Drive	Tracțiune față	HP	163 / 120

INSPECTION DETAILS

Inspection Date	12/06/2024 15:32:58	Inspection Location	TRITON INTERNATIONAL CARGO SRL
-----------------	---------------------	---------------------	-----------------------------------



DOCUMENT LIST		ACCESSORIES		REMOVABLE ITEMS	
Audio Manual	✗	Delivery Condition Report	✗	6 Airbag	✓
Emmissions Cert	✗	Euro Sticker	✗	ABS	✓
Insurance	✗	Original Key	✓	Air Condition Automatic	✓
Owners Manual	✓	Registration Form	✗	Audio AM/FM Stereo	✓
Service Manual	✗	Spare Key	✗	Automatic Transmission	✓
Tax Sticker	✗	Transport Licence	✗	Central Arm Rest	✓
				Central Locking	✓
				Cruise Control	✓
				Dashboard Computer	✓
				Fog Lights	✓
				Heated Seats	✓
				Key Remote Entry	✓
				Lights Xenon	✓
				Multifunctional Steering Wheel	✓
				Navigation System	✓
				Outside Mirror Heating	✓
				Outside Mirror Power	✓
				Parking Sensors	✓
				Power Steering	✓
				Power Windows	✓
				Steering Wheel Leather	✓
				Tail Board	✓

TYRES					
Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Boot 1	5 mm	Marca nerecunoscuta	17	225/60	Summer
Boot 2	6 mm	Marca nerecunoscuta	17	225/60	Summer
Boot 3	5 mm	Marca nerecunoscuta	17	225/60	Summer
Boot 4	5 mm	Marca nerecunoscuta	17	225/60	Summer
Front Left	5 mm	Continental	16	205/60	Winter
Front Right	5 mm	Continental	16	205/60	Winter
Rear Left	5 mm	Continental	16	205/60	Winter
Rear Right	5 mm	Continental	16	205/60	Winter

EXCEPTION / DAMAGE

1



Part	Door - Left Front
Type	Scratch
Severity	4 cm - 6 cm
Repair Mode	No Action
Cause	In Service

INTERIOR DAMAGES

2

A photograph of the driver's side seat in a car, showing a dark-colored seat with a light-colored stain on the lower part of the backrest and seat cushion.

Part	Seat - Left Front
Type	Stained / Soiled
Severity	Over 30 cm
Repair Mode	Clean
Cause	In Service

INSPECTION CHECKLIST	
Smoker : No	Vehicle Not Driveable : No

COMMENTS

Auto foarte murdar daune nevizibile,Pornire motor – da ,Funct. lumini –da ,Funct. geamuri – da ,Funct. Oglinzi - da, Servo - da, Sist. audio – da ,Martori bord aprinsi -da,Zgomot anormal motor -da, Capac capsulare motor -,da Element insonorizare capota –da,Cutie de viteze-automata, Frane normal, Esapament -normal, Centuri de sig. -da.



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Ref 1 ;



Ref 1 ;



Ref 2 ;



Ref 2 ;