

**VEHICLE APPRAISAL REPORT**

VEHICLE DETAILS			
Vin Number	VF3YCBPDC12W40871	Plate	B164GEA
Make	PEUGEOT	Model	Boxer
Registration Date	05/10/2023	Interior Colour	Black
Smog Certificate Date	25/02/2025	Maintenance Odometer 0	
Gears	6	Gear Type	Transmisie manuală
Fuel Type	Diesel	Drive	Tracțiune față
Odometer	68925	Body Type/Doors	Utilitara/2
Maintenance Date	25/02/2025	Exterior Colour	White
Seats	3	HP	140 / 103

INSPECTION DETAILS			
Inspection Date	25/02/2025 10:20:12	Inspection Location	TRITON INTERNATIONAL CARGO SRL



DOCUMENT LIST		ACCESSORIES		REMOVABLE ITEMS	
Audio Manual	✗	Delivery Condition Report	✗	1 Airbag	✓
Emmissions Cert	✗	Euro Sticker	✗	AC - Working: YES	✓
Insurance	✗	Original Key	✓	Cruise Control	✓
Owners Manual	✗	Registration Form	✗	Emergency Kit	✓
Service Manual	✗	Spare Key	✗	Hubcap Front Left	✓
Tax Sticker	✗	Transport Licence	✗	Oil Level: Max	✓
				Outside Mirror Power	✓
				Ram	✓
				Steering Wheel Multifunction	✓
				Window Power Front	✓
				ABS	✓
				Audio AM/FM Stereo	✓
				Dashboard Computer	✓
				Front Air Conditioning	✓
				Key Remote Entry	✓
				Outside Mirror Heating	✓
				Power Steering	✓
				Spare Wheel	✓
				Warning Triangle	✓

TYRES					
Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Spare	7 mm	Michelin	15	225/70	Summer
Front Left	6 mm	Marca nerecunoscuta	15	225/70	Winter
Front Right	6 mm	Marca nerecunoscuta	15	225/70	Winter
Rear Left	6 mm	Marca nerecunoscuta	15	225/70	Winter
Rear Right	6 mm	Marca nerecunoscuta	15	225/70	Winter

EXCEPTION / DAMAGE							
1		Part	Pillar - Left Front	2		Part	Pillar - Left Front
		Type	Moulding/Emblem/Strip Missing			Type	Moulding/Emblem/Strip Missing
		Severity	Missing			Severity	Missing
		Repair Mode	Remove & Replace			Repair Mode	Remove & Replace
		Cause	In Service			Cause	In Service
3		Part	Boot Lid - Rear				
		Type	Moulding/Emblem/Strip Missing				
		Severity	Missing				
		Repair Mode	No Action				
		Cause	In Service				

**INTERIOR DAMAGES**

INSPECTION CHECKLIST	
Smoker : No	Vehicle Not Driveable : No

**COMMENTS**

Ref.3 se refera la structura metalica + prelata lipsa.Auto inspectat in parcul CAT din com. Ciorogarla.Pornire motor – da ,Funct. lumini –da ,Funct. geamuri – da ,Funct. Oglinzi - da, Servo - da, Sist. audio – da ,Martori bord aprinsi -da,Zgomot anormal motor -da, Capac capsulare motor -,nu Element insonorizare capota –nu,Cutie de viteze-manuala, Frane normal, Esapament - normal, Centuri de sig. -da.



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Ref 1 ;



Ref 1 ;



Ref 2 ;



Ref 2 ;



Ref 3 ;



Ref 3 ;



Ref 3 ;



Ref 3 ;



Ref 3 ;



Ref 3 ;