

VEHICLE APPRAISAL REPORT

VEHICLE DETAILS					
Vin Number	VF3YDBPFCNG022158	Plate	B165GEA	Odometer	64569
Make	PEUGEOT	Model	Boxer	Body Type/Doors	Utilitara/4
Registration Date	05/10/2023	Interior Colour	Black	Exterior Colour	White
Smog Certificate Date	25/02/2025	Maintenance Odometer	0	Maintenance Date	25/02/2025
Gears	6	Gear Type	Transmisie manuală	Seats	3
Fuel Type	Diesel	Drive	Tracțiune față	HP	140 / 103

INSPECTION DETAILS		
Inspection Date	25/02/2025 10:40:08	Inspection Location
		TRITON INTERNATIONAL CARGO SRL



DOCUMENT LIST				ACCESSORIES				REMOVABLE ITEMS			
Audio Manual	✗	Delivery Condition Report	✗	1 Airbag	✓	ABS	✓				
Emmissions Cert	✗	Euro Sticker	✗	AC - Working: YES	✓	Audio AM/FM Stereo	✓				
Insurance	✗	Original Key	✓	Central Arm Rest	✓	Cruise Control	✓				
Owners Manual	✗	Registration Form	✗	Dashboard Computer	✓	Emergency Kit	✓				
Service Manual	✗	Spare Key	✗	Fire Extinguisher	✓	Fog Lights	✓				
Tax Sticker	✗	Transport Licence	✗	Front Air Conditioning	✓	Hubcap Front Left	✓				
				Key Remote Entry	✓	Oil Level: Max	✓				
				Outside Mirror Heating	✓	Outside Mirror Power	✓				
				Park Distance Control Rear	✓	Power Steering	✓				
				Ram	✓	Spare Wheel	✓				
				Steering Wheel Multifunction	✓	Warning Triangle	✓				
				Window Power Front	✓						

TYRES					
Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Spare	8 mm	Michelin	16	215/75	Summer
Front Left	6 mm	Marca neregunoscuta	16	215/75	Winter
Front Right	6 mm	Marca neregunoscuta	16	215/75	Winter
Rear Left	6 mm	Marca neregunoscuta	16	215/75	Winter
Rear Right	6 mm	Marca neregunoscuta	16	215/75	Winter

EXCEPTION / DAMAGE

1



Part	Quarter Panel (For LCV) - Right Rear
Type	Multiple Dents
Severity	15 cm - 20 cm
Repair Mode	Repair Metal / Refinish
Cause	In Service

2



Part	Cargo Doors - Rear
Type	Multiple Dents
Severity	15 cm - 20 cm
Repair Mode	Repair Metal / Refinish
Cause	In Service

3



Part	Quarter Panel (For LCV) - Left Rear
Type	Multiple Dents
Severity	15 cm - 20 cm
Repair Mode	Repair Metal / Refinish
Cause	In Service

INTERIOR DAMAGES

INSPECTION CHECKLIST	
Smoker : No	Vehicle Not Driveable : No

COMMENTS

Auto inspectat in parcul CAT din com. Ciorogarla.Pornire motor – da ,Funct. lumini –da ,Funct. geamuri – da ,Funct. Oglinzi - da, Servo - da, Sist. audio – da ,Martori bord aprinsi -da,Zgomot anormal motor -da, Capac capsulare motor -,nu Element insonorizare capota –nu,Cutie de viteze-manuala, Frane normal, Esapament - normal, Centuri de sig. -da.



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Ref 1 ;



Ref 1 ;



Ref 2 ;



Ref 2 ;



Ref 3 ;



Ref 3 ;