



MAN CAMION

TGX 18.480

VIN	WMA06XZZ0FM667129
Registration	B105EAB
Mileage	172,185 km
First registration date	01/01/2015
Body colour	White

INSPECTION DETAILS

Inspection date	19/05/2025 14:19:07
-----------------	---------------------

VEHICLE INFO

Make	MAN
Model	Camion
Version	TGX 18.480
VIN	WMA06XZZ0FM667129
Registration	B105EAB
First registration date	01/01/2015

Fuel type	Diesel
Mileage	172,185 km
Number of seats	2
Interior colour	Black
Body colour	White

DOCUMENTS AND MAINTENANCE

Number of keys total	1	Registration certificate original	Yes	Type of Maintenance book	Digital maintenance
----------------------	---	-----------------------------------	-----	--------------------------	---------------------

EQUIPMENT ACCORDING TO INSPECTOR

Abnormal engine noises	Yes	Head-up Display	No	Type of climate control	Autom climate control
Adaptive cruise control	Yes	Metalic paint	No	Type of headlighting	Headlighting Halogen
Airco functioning	No	Mirrors functioning	Yes	Type of Lining	Lining fabrics
All seatbelts functional, damage free	All seatbelts OK	Number of charging cables (normal)	0	Type of Tow bar	No Tow bar
Cruise Control	Yes	Number of charging cables (rapid charge)	0	Vehicle running	No
First aid kit	No	Power steering functioning	Yes	Windows electric F	Yes
Functioning headlight L	Yes	Radio multimedia	Yes	Windows electric functioning	Yes
Functioning headlight R	Yes	Steering wheel multifunctional	Yes		

TIRES

Position	Tread	Manufacturer	Dimensions	Tire season	Type of rims	Runflat
Front Left	5.0 mm	Pirelli	385/55 R 22 160 K	Winter	Steel	No
Front Right	5.0 mm	Pirelli	385/55 R 22 160 K	Winter	Steel	No
Rear Left	7.0 mm	Other	315/70 R 22 150 L	Winter	Steel	No
Rear Right	7.0 mm	Other	315/70 R 22 150 L	Winter	Steel	No

EXTERIOR DAMAGES



2 | BONNET

Type	Stone chip(s)
Repair mode	Paint



3 | BUMPER F

Type	Scratch(es)
Repair mode	Paint



4 | BUMPER F

Type	Scratch(es)
Repair mode	Paint




5 | GRILLE

Type	Crack
Repair mode	Replace



6 | SILL TRIM L

Type	Crack
Repair mode	Replace and paint



7 | DOOR FL

Type	Scratch(es)
Repair mode	Paint



8 | WHEEL ARCH COVER RL

Type	Crack
Repair mode	Replace



9 | REAR LIGHT R

Type	Crack
Repair mode	Replace



10 | WHEEL ARCH COVER RR

Type	Crack
Repair mode	Replace



11 | DOOR FR

Type	Scratch(es)
Repair mode	Paint



12 | SILL TRIM R

Type	Crack
Repair mode	Replace and paint

INTERIOR DAMAGES



1 | SEAT COVER FL

Type	Burned
Repair mode	No repair

COMMENTS

i INSPECTOR COMMENTS

Auto prezinta zgârieturi și infundaturi superficiale,Auto prezinta urme de reparații posibile neconforme.

COMMERCIAL PHOTOS

