



Citroën Jumper

2.2

VIN	VF7YDBNFC12S91225
Registration	B112WJX
Mileage	242,651 km
First registration date	12/07/2021
Body colour	White

INSPECTION DETAILS

Inspection date	24/07/2025 14:36:50	Inspection location	Parc Benga
-----------------	---------------------	---------------------	------------

VEHICLE INFO

Make	Citroën	Fuel type	Diesel
Model	Jumper	Mileage	242,651 km
Version	2.2	Number of seats	3
VIN	VF7YDBNFC12S91225	Interior colour	Black
Registration	B112WJX	Body colour	White
First registration date	12/07/2021		

DOCUMENTS AND MAINTENANCE

Number of keys total	1	Type of Maintenance book	Digital maintenance
Registration certificate original	Yes	User's manual	Yes

EQUIPMENT ACCORDING TO INSPECTOR

Abnormal engine noises	No	Number of charging cables (rapid charge)	0
Airco functioning	Yes	Power steering functioning	Yes
All seatbelts functional, damage free	All seatbelts OK	Spare wheel	Yes
First aid kit	No	Type of climate control	Manual climate control
Functioning headlight L	Yes	Type of headlighting	Headlighting Halogen

Functioning headlight R	Yes
Head-up Display	No
Metalic paint	No
Mirrors functioning	Yes
Number of charging cables (normal)	0

Type of Lining	Lining fabrics
Type of Tow bar	No Tow bar
Vehicle running	No
Windows electric F	Yes
Windows electric functioning	Yes

TIRES

Mounted Tires

Location	Position	Tread	Manufacturer	Dimensions	Tire season	Type of rims	Runflat
Front	Left	4.0 mm	Other	225/75 R 16 116 R	Winter	-	No
Front	Right	4.0 mm	Other	225/75 R 16 116 R	Winter	-	No
Rear	Left	7.0 mm	Michelin	225/75 R 16 116 R	Summer	-	No

Spare wheel

Location	Position	Tread	Manufacturer	Dimensions	Tire season	Type of rims	Runflat
-	-	6.0 mm	Other	225/75 R 16 110 R	Winter	Steel	-

DAMAGES

Exterior damages



5 | Bumper F

Type	Crack
Repair mode	Replace



6 | Bumper trim F

Type	Missing
Repair mode	Replace



7 | Bonnet

Type	Dent(s) and scratch(es)
Repair mode	Repair and paint (complete)



8 | Bumper R

Type	Dent(s)
Repair mode	Replace



9 | Tailgate / Boot

Type	Dent(s)
Repair mode	Repair and paint (complete)

Interior damages



1 | Interior

Type	Broken
Repair mode	Replace



2 | Interior

Type	Broken
Repair mode	Replace



3 | Interior

Type	Broken
Repair mode	Replace



4 | Door panel trim RR

Type	Crack
Repair mode	Replace

COMMENTS

Inspector comments

Martori bord aprinși. Pneu de rezerva pana.Auto prezintă multiple zgârieturi și infundături superficiale.

Commercial photos

