

VEHICLE APPRAISAL REPORT





VEHICLE DETAILS					
Vin Number	XLRTEH4300G264231	Plate	B500BBS	Odometer	814686
Make	Daf	Model	XF	Body Type/Doors	Utilitara de mare capacitate/2
Registration Date	17/04/2019	Interior Colour	Black	Exterior Colour	White
Smog Certificate Date	18/07/2024	Maintenance Odometer	0	Maintenance Date	18/07/2024
Gears	0	Gear Type	Automată	Seats	2
Fuel Type	Diesel	Drive	Tracțiune spate	HP	483 / 355

INSPECTION DETAILS			
Inspection Date	18/07/2024 11:16:43	Inspection Location	TRITON INTERNATIONAL CARGO SRL



DOCUMENT LIST		ACCESSORIES		REMOVABLE ITEMS					
Audio Manual	✗	Delivery Condition Report	✗	ABS	✓	Audio CD Player	✓		
Emmissions Cert	✗	Euro Sticker	✗	Central Locking	✓	Cruise Control	✓		
Insurance	✗	Original Key	✓	Dashboard Computer	✓	Fog Lights	✓		
Owners Manual	✗	Registration Form	✗	Front Electric Window	✓	Key Remote Entry	✓		
Service Manual	✗	Spare Key	✗	Multifunctional Steering Wheel	✓	Outside Mirror Heating	✓		
Tax Sticker	✗	Transport Licence	✗	Outside Mirror Power	✓	Power Steering	✓		
				Transmission Auto	✓				

TYRES						
	Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
	Front Left	8 mm	Michelin	22	385/65	Summer
	Front Right	8 mm	Michelin	22	385/65	Summer
	Inner Rear Left	8 mm	Michelin	22	315/70	Summer
	Inner Rear Right	8 mm	Michelin	22	315/70	Summer
	Rear Left	8 mm	Michelin	22	315/70	Summer
	Rear Right	8 mm	Michelin	22	315/70	Summer

EXCEPTION / DAMAGE							
1		Part	Door - Left Front	2		Part	Side View Mirror - Left Front
		Type	Dented w/ Paint Dmg			Type	Scratch
		Severity	6 cm - 8 cm			Severity	4 cm - 6 cm
		Repair Mode	No Action			Repair Mode	No Action
		Cause	In Service			Cause	In Service
3		Part	Fog Lamp - Front	4		Part	Bumper - Front
		Type	Malfunction			Type	Scratch
		Severity	4 cm - 6 cm			Severity	15 cm - 20 cm
		Repair Mode	No Action			Repair Mode	No Action
		Cause	In Service			Cause	In Service
5		Part	Windshield - Front	6		Part	Rocker Panel - Right Front
		Type	Chipped			Type	Scratch
		Severity	3 cm - 4 cm			Severity	Over 30 cm
		Repair Mode	No Action			Repair Mode	No Action
		Cause	In Service			Cause	In Service
7		Part	Side View Mirror - Right Front	8		Part	Fender / Wing - Right Front
		Type	Scratch			Type	Scratch
		Severity	10 cm - 15 cm			Severity	4 cm - 6 cm
		Repair Mode	No Action			Repair Mode	No Action
		Cause	In Service			Cause	In Service

