

VEHICLE APPRAISAL REPORT

VEHICLE DETAILS			
Vin Number	XLRTEH4300G101927	Plate	B520BBS
Make	Daf	Model	XF
Registration Date	03/03/2016	Interior Colour	Black
Smog Certificate Date	18/07/2024	Maintenance Odometer	0
Gears	0	Gear Type	Automată
Fuel Type	Diesel	Drive	Tracțiune spate
Odometer	1045394	Body Type/Doors	Utilitara de mare capacitate/2
		Exterior Colour	Red
		Maintenance Date	18/07/2024
		Seats	2
		HP	510 / 375

INSPECTION DETAILS		
Inspection Date	18/07/2024 11:32:14	Inspection Location
		TRITON INTERNATIONAL CARGO SRL



DOCUMENT LIST		ACCESSORIES		REMOVABLE ITEMS
Audio Manual	✗	Delivery Condition Report	✗	
Emmissions Cert	✗	Euro Sticker	✗	
Insurance	✗	Original Key	✓	
Owners Manual	✗	Registration Form	✗	
Service Manual	✗	Spare Key	✗	
Tax Sticker	✗	Transport Licence	✗	
		ABS	✓	
		Audio AM/FM Stereo	✓	
		Cruise Control	✓	
		Fog Lights	✓	
		Key Remote Entry	✓	
		Outside Mirror Heating	✓	
		Power Steering	✓	
		Air-Conditioning	✓	
		Central Locking	✓	
		Dashboard Computer	✓	
		Front Electric Window	✓	
		Multifunctional Steering Wheel	✓	
		Outside Mirror Power	✓	
		Transmission Auto	✓	

TYRES					
	Position	Tread	Manufacturer	Diameter	Tyre Season
	Front Left	8 mm	Michelin	22	385/65
	Front Right	8 mm	Michelin	22	385/65
	Inner Rear Left	8 mm	Michelin	22	315/70
	Inner Rear Right	8 mm	Michelin	22	315/70
	Rear Left	8 mm	Michelin	22	315/70
	Rear Right	8 mm	Michelin	22	315/70

EXCEPTION / DAMAGE					
1		Part	Fender / Wing - Left Front	2	
	Type	Scratch			Type
	Severity	6 cm - 8 cm			Severity
	Repair Mode	No Action			Repair Mode
	Cause	In Service			Cause
3		Part	Door - Left Front	4	
	Type	Scratch			Type
	Severity	10 cm - 15 cm			Severity
	Repair Mode	No Action			Repair Mode
	Cause	In Service			Cause
5		Part	Fog Lamp - Front	6	
	Type	Broken			Type
	Severity	10 cm - 15 cm			Severity
	Repair Mode	No Action			Repair Mode
	Cause	In Service			Cause
7		Part	Windshield - Front	8	
	Type	Cracked			Type
	Severity	25 cm - 30 cm			Severity
	Repair Mode	No Action			Repair Mode
	Cause	In Service			Cause
					Side View Mirror - Right Front
					Scratch
					Severity
					10 cm - 15 cm
					Repair Mode
					No Action
					Cause
					In Service

9		Part	Fender / Wing - Right Front	Type	Moulding/Emblem/Strip Damage	Severity	Over 30 cm	Repair Mode	No Action	Cause	In Service
10		Part	Door - Right Front	Type	Dented, No Pnt Dmg	Severity	6 cm - 8 cm	Repair Mode	No Action	Cause	In Service
11		Part	Fender / Wing - Right Rear	Type	Moulding/Emblem/Strip Damage	Severity	10 cm - 15 cm	Repair Mode	No Action	Cause	In Service
12		Part	Fender / Wing - Left Rear	Type	Moulding/Emblem/Strip Damage	Severity	10 cm - 15 cm	Repair Mode	No Action	Cause	In Service
13		Part	Side Panel - Left Rear	Type	Dented, No Pnt Dmg	Severity	10 cm - 15 cm	Repair Mode	No Action	Cause	In Service

INTERIOR DAMAGES

14		Part	A-Post Pillar Trim - Left Front	Type	Moulding/Emblem/Strip Damage	Severity	3 cm - 4 cm	Repair Mode	No Action	Cause	In Service
----	--	------	---------------------------------	------	------------------------------	----------	-------------	-------------	-----------	-------	------------

INSPECTION CHECKLIST

Smoker : No
Vehicle Not Driveable : No

COMMENTS

Volan uzat,Auto a fost inspectat in locatia CAT autologistik,+1 Pat,+Frigider,Baterie descarcata,KM din Tahograful nu este in concordanta cu KM din bord,Pornire motor – da ,Funct. lumini –da ,Funct. geamuri – da ,Funct. Oglinzi - da, Servo - da, Sist. audio – da ,Martori bord aprinsi -da,Zgomot anormal motor -da, Capac capsulare motor -,nu Element insonorizare capota –nu,Cutie de viteze-automata, Frane normal, Esapament - normal, Centuri de sig. -da.



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Ref 1 ;



Ref 1 ;



Ref 2 ;



Ref 2 ;



Ref 3 ;



Ref 3 ;



Ref 4 ;



Ref 4 ;



Ref 5 ;



Ref 5 ;




Ref 6 ;



Ref 6 ;



Ref 7 ;



Ref 7 ;



Ref 8 ;



Ref 8 ;



Ref 9 ;



Ref 9 ;



Ref 10 ;



Ref 10 ;



Ref 11 ;



Ref 11 ;



Ref 12 ;



Ref 12 ;



Ref 13 ;



Ref 13 ;



Ref 14 ;



Ref 14 ;