

VEHICLE APPRAISAL REPORT

VEHICLE DETAILS

Vin Number	WK0S0002400189977	Plate	B57VLN	Odometer	0
Make	Kogel	Model	S24-1	Body Type/Doors	Utilitara de mare capacitate/1
Registration Date	01/01/2016	Interior Colour	White	Exterior Colour	White
Smog Certificate Date	11/05/2023	Maintenance Odometer	0	Maintenance Date	11/05/2023
Gears	0	Gear Type	Nealocat	Seats	0
Fuel Type	Nealocat	Drive	Tracțiune spate	HP	0 / 0

INSPECTION DETAILS

Inspection Date	11/05/2023 12:20:50	Inspection Location	TRITON INTERNATIONAL CARGO SRL
-----------------	---------------------	---------------------	--------------------------------



DOCUMENT LIST

Audio Manual	✗	Delivery Condition Report	✗
Emmissions Cert	✗	Euro Sticker	✗
Insurance	✗	Owners Manual	✗
Registration Form	✗	Service Manual	✗
Spare Key	✗	Tax Sticker	✗
Transport Licence	✗		

ACCESSORIES

ABS	✓
-----	---

REMOVABLE ITEMS

TYRES

Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Front Right	7 mm	Goodyear	19	435/50	Summer
Inner Rear Left	8 mm	Continental	19	435/50	Summer
Inner Rear Right	7 mm	Goodyear	19	435/50	Summer
Front Left	8 mm	Continental	19	435/50	Winter
Rear Left	7 mm	Marca nerecunoscuta	19	435/50	Winter
Rear Right	7 mm	Marca nerecunoscuta	19	435/50	Winter

EXCEPTION / DAMAGE

1		Part	Side Panel - Right Rear
		Type	Cut
		Severity	Over 30 cm
		Repair Mode	No Action
		Cause	In Service

INTERIOR DAMAGES

INSPECTION CHECKLIST

Smoker : No Vehicle Not Driveable : No

COMMENTS

Prima dauna care necesita vopsire include constanta materialelor de vopsire si pregatire a vopselei pentru vopsitorie.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Any holder of this document is advised that information contained hereon is limited to the visual examination of the Vehicle and at the time of inspection of the Vehicle and does not rise to the level of a mechanical diagnostic examination performed by a qualified mechanic using appropriate diagnostic equipment. This visual inspection was carried out without any dismantling or test-drive of the Vehicle and is based solely on the specifically agreed criteria as described in this document without any other criteria being taken into account.



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Standard



Ref 1 ;



Ref 1 ;